



Upper Occoquan Service Authority

Leader in Water Reclamation and Reuse

14631 COMPTON ROAD, CENTREVILLE, VIRGINIA 20121-2506
(703) 830-2200

TO ALL RECIPIENTS:

For UOSA

SUBJECT: Addendum #

The above numbered solicitation is amended as set forth below. The hour and date specified for receipt of offers:

☐ is not extended

☐ is extended

OFFERORS MUST ACKNOWLEDGE receipt of this Addendum by one of the following methods:

- a. By acknowledgement of this Addendum on Submission Form submitted with the proposal;
- b. By referencing its receipt in your Transmittal Letter

If by virtue of this Addendum you desire to change a proposal already submitted, such change may be made by letter, provided it includes reference to the solicitation and this Addendum and is received prior to the due hour and date specified.

DESCRIPTION OF ADDENDUM:

All other Terms, Conditions, Tables, Charts and Specifications, and Drawings not otherwise changed remain as originally stated or as shown.

ISSUED BY:

Upper Occoquan Service Authority

Date

UOSA IFB 21-17 Addendum#1, Attachment A

1. Is any level of security clearance required;

No level of security clearance is required.

2. IFB mentions mold inspection and remediation services. On Attachment D: are you just asking the price per square foot for mold remediation?

Yes, we are requesting price per square foot as referenced in 2.4 Task Areas.

3. For mold remediation, would we be responsible for put-back? 2.3 L: The contractor shall return all work areas to the same or better condition than prior to start of work.

Yes, the Contractor is responsible for returning area to same or better condition as referenced in 2.3. This predominately refers to the placement of furniture and/or equipment and cleaning materials used and removed from area. The responsibility of repair to walls (drywall) or floors (carpet/tile) will be negotiated/delineated when Task order is written. Repair work may be given to different Contractor if in UOSA best interest.